

Pictures taken of project work at:

# Headlines Salon

70 New Road  
Llandeilo, SA19 6DF  
Wales, United Kingdom

## Work Tasks:

1. Washbasins repaired
2. Washbasins re-enamelled in high-gloss black
3. Wood panelling repaired
4. Wood panelling resurfaced in stone fleck granite effect
5. All work completed on-site during closed periods without any business disruption

Completion time: 3 days



Fig1: Basins re-enamelled in high-gloss black and panels resurfaced in stone fleck granite effect





Fig2: Before and After





Fig3: Before and After





Fig4: Before and After





Fig5: After pictures of stone fleck granite effect

